

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA Division Director

Minerals Inspection Report

04/10/2015

Reviewed

Report Date: 04/10/2015							
Mine Name: Pine Ridge Rock Products	Permit Number:	S/057/0010	Mine Status:	Active			
Operator Name: Pine Ridge Excavation and Landscapes	Inspection Date:	03/31/2015	Permit Fees:	Paid			
Inspector(s): M. Bradley	Inspection Time:	10:00am	Bond Amount:	\$58,700			
Attendee(s): Iris Hennon, Rhonda Kippen, Jim Gentry, Weber	Weather:	pt.cloudy, mild	Bond Escalation:	09/30/2019			
Inspection Purpose: Follow up from enforcement	Prior Inspection:	09/18/2014					

Conclusions and Recommendations

Location: 427966.00 mE, 4582746.00 mN. Purpose was to follow up after getting permitting completed. Site appears to have expanded a bit. Road leading to southeast area was blocked off by large rocks, apparently at the direction of MSHA. Blocked off area is where the safety station is located, but is accessible from road southwest of there. Weber County halted operations until Conditional Use Permit is in order. Only surface plucking from existing roads is allowed. No blasting and no crusher on site as reported. There is a portable sorter and a pair of grizzlies on site.

	Elements of Inspection	Evaluated & Commented	Enforcement
1.	Permits, Revisions, Transfer, Bonds	\boxtimes	
	DOGM permit is in order, bond provided, and MR-RC signed. Weber County CUP in works	. Awaiting Cultural clearance	ce.
2.	Public Safety (shafts, adits, trash, signs, highwalls)	\boxtimes	
	Some trash on site, empty containers, etc. Not as bad as previous.		
3.	Protection of Drainages/Erosion Control		
4.	Deleterious Material		
5.	Roads (maintenance, surfacing, dust control, safety)		
6.	Reclamation	\boxtimes	
	Some areas under reclamation, pending revegetation.		
7.	Backfilling/Grading (trenches, pits, roads, highwalls, shafts)	\boxtimes	
	Some regrading in progress, more planned		
8.	Soils		
	Topsoil from new areas being stockpiled		
9.	Revegetation	\boxtimes	
	Pending		
10.	Other		

Inspector's	Signature:
-------------	------------

CC: Iris Hennon, Weber County Planning (ihennon@co.weber.ut.us); Dan Lockwood, PREA (dan@pineridgeutah.com)

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M057-Weber/S0570010-PineRidge/inspections/INSP-03242015.pdf



S/057/0010 Mine: Page 2 of 3


Inspected: 03/31/2015



Portable sorter



Parked dozer in main working area



Grizzlies used to store materials



Trackhoes on north end of site



Mine: S/057/0010
Page 3 of 3

Page 3 o




Trackhoes in area under regrading for reclamation



Area at northwest portion to be regraded



Area to be regraded with topsoil stockpile in background



West portion of area pushed out to USFS boundary

